

CEN23LA266

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right side of wreckage (Courtesy of Federal Aviation Administration)



Photograph 2 - Under side Left wing (Courtesy of Federal Aviation Administration)