

CEN23LA267

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Fuselage during postaccident examination (NTSB Photo)



Photograph 2 - Rudder during postaccident examination (NTSB Photo)




Photograph 3 - Stabilizer during postaccident examination (NTSB Photo)



Photograph 4 - Right wing during postaccident examination (NTSB Photo)




Photograph 5 - Left wing during postaccident examination (NTSB Photo)




Photograph 6 - Right engine test run image (NTSB Photo)




Photograph 7 - Left engine during postaccident examination (NTSB Photo)



Photograph 8 - Left engine camshaft gear (NTSB Photo)



Photograph 9 - Left engine accessory gears (NTSB Photo)



Photograph 10 - Left engine starter drive adapter (NTSB Photo)