

CEN23LA268

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Fragmented Airplane (Courtesy of NTSB)**



**Photograph 2 - Vertical Stabilizer (Courtesy of NTSB)**



**Photograph 3 - Left Fuel Cap with Cracked O-Ring (Courtesy of NTSB)**



**Photograph 4 - Right Fuel Cap with Cracked O-Ring (Courtesy of NTSB)**