

CEN23LA271

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left Wing Leading Edge (Courtesy of FAA)



Photograph 2 - Damaged Rudder (Courtesy of FAA)



Photograph 3 - Damaged Left Flap (Courtesy of FAA)