

CEN23LA306

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Impact and debris field (Courtesy of the Federal Aviation Administration)



Photograph 2 - Separated landing gear and tail boom (Courtesy of Federal Aviation Administration)



Photograph 3 - Main wreckage (Courtesy of Federal Aviation Administration)