

CEN23LA311

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Propeller and right view of airplane (Courtesy of the FAA)



Photograph 2 - Tears to the aluminum skin of the right aileron (Courtesy of the FAA)