

CEN23LA319

INVESTIGATION PHOTOGRAPH



Photograph 1 - Accident glider tail boom (Source: Federal Aviation Administration)



Photograph 2 - Damaged tail boom (Source: Federal Aviation Administration)