

CEN23LA334


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Black skid marks leading to wreckage from taxiway C (Courtesy of FAA)



Photograph 2 - Substantially damaged right wing (Courtesy of FAA)



Photograph 3 - View looking aft of airplane at the accident site (Courtesy of FAA)



Photograph 4 - Right brake caliper assembly (Courtesy of NTSB)



Photograph 5 - Right brake master cylinder (Courtesy of Air Tractor)



Photograph 6 - Right main wheel assembly and brake disc (Courtesy of NTSB)



Photograph 7 - Brake fluid recovered from right brake system (Courtesy of NTSB)



Photograph 8 - Airframe as examined after recovery (Courtesy of Air Tractor)