


CEN23LA337

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Forward lower fuselage and right main landing gear attach area; localized skin crushing and wrinkling near the fractured gear fitting. (Courtesy of FAA)



Photograph 2 - Right aileron, outboard trailing-edge damage (Courtesy of FAA)



Photograph 3 - Engine compartment, left front view with cowling removed (Courtesy of FAA)



Photograph 4 - Engine compartment, right front view with cowling removed (Courtesy of FAA)



Photograph 5 - Induction airbox and fuel servo detail; throttle and mixture linkages and fuel supply line visible (Courtesy of FAA)