

CEN23LA339

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of airplane and deformation noted to the left wing (Courtesy of FAA)



Photograph 2 - Deformation noted to the rudder and vertical stabilizer (Courtesy of FAA)



Photograph 3 - Tears in the firewall and deformation to the engine mount (Courtesy of FAA)