

CEN23LA348

INVESTIGATION PHOTOGRAPHS



Photograph 1 -Damaged Empennage (Courtesy of FAA)



Photograph 2 - Damaged Left Wing and Lift Strut (Courtesy of FAA)