

CEN23LA350

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the right side of the helicopter at the accident site, during night conditions (Courtesy of Air Evac Lifeteam)



Photograph 2 - View of the left side of the helicopter at the accident site, during night conditions (Courtesy of Air Evac Lifeteam)



**Photograph 3 - View of the left side of the helicopter at the accident site, during day conditions
(Courtesy of the Federal Aviation Administration)**



**Photograph 4 - View of the front of the helicopter at the accident site, during day conditions
(Courtesy of the Federal Aviation Administration)**



Photograph 5 - View of the right side of the helicopter at the accident site, during day conditions (Courtesy of the Federal Aviation Administration)



Photograph 6 - View of the empennage at the accident site, during day conditions (Courtesy of the Federal Aviation Administration)



Photograph 7 - View of the vertical stabilizer and the fence at the accident site, during day conditions (Courtesy of the Federal Aviation Administration)



**Photograph 8 - View of the damage sustained to the tail boom and the tail rotor driveshaft.
(Courtesy of the Federal Aviation Administration)**



Photograph 9 - View of the damage sustained to one of the tail rotor blades (Courtesy of the Federal Aviation Administration)



Photograph 10 - View of the damage sustained to the one of the tail rotor blades (Courtesy of the Federal Aviation Administration)