

CEN23LA355

INVESTIGATION PHOTOGRAPH



Photograph 1 - Bent and wrinkled airframe firewall (Courtesy of Operator)