

CEN23LA357

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage to Left Wing (Courtesy of FAA)



Photograph 2 - Damage to Empennage (Courtesy of FAA)