

CEN23LA365

INVESTIGATION PHOTOGRAPHS



Photograph 1 -Tailwheel assembly displaced to the right (Courtesy of FAA)



Photograph 2 - Substantial damage to tailwheel supporting structure (Courtesy of FAA)