



Photo 1 – Right wing damage (Source: FAA)



Photo 2 – Vertical stabilizer and rudder damage (Source: FAA)



Photo 3 – Runway excursion tire marks (Source: FAA)