

CEN23LA370

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Overview (Courtesy of Durant Airport Director)



Photograph 2 - Right Engine (Courtesy of Lycoming Engines)



Photograph 3 - No. 2 Piston and Connecting Rod (Courtesy of Lycoming Engines)



Photograph 4 - No. 2 Piston Head (Courtesy of Lycoming Engines)



Photograph 5 - No. 2 Connecting Rod Cap (Courtesy of Lycoming Engines)