

CEN23LA393

INVESTIGATION PHOTOGRAPH



Photograph 1 - Left wing rear spar is bent and buckled (Courtesy of Wisconsin State Patrol)