

CEN23LA399

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the front of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 2 - View of the right side of the airplane at the accident site (courtesy of the Federal Aviation Administration)




Photograph 3 - View of the rear of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 4 - View of the rear of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 5 - View of the left side of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 6 - View of the right side of the engine at the accident site (courtesy of the Federal Aviation Administration)




Photograph 7 - View of the left side of the engine at the accident site (courtesy of the Federal Aviation Administration)



Photograph 8 - View of the fractured engine mount (courtesy of Missouri Aviation, Inc.)



Photograph 9 - View of the rear of the engine during the engine examination



Photograph 10 - View of the bottom of the engine during the engine examination



Photograph 11 - View of the front of the engine during the engine examination



Photograph 12 - View of the left side of the engine during the engine examination