

CEN23LA400

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Substantially Damaged Right Wing (Courtesy of FAA)