

CEN23LA402


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane, right side (Courtesy of FAA)



Photograph 2 - Structural damage (Courtesy of FAA)



Photograph 3 - Structural damage (Courtesy of FAA)




Photograph 4 - Alternator No. 2, belt missing (Courtesy of FAA)



Photograph 5 - Broken belt from alternator No. 2 (Courtesy of FAA)



Photograph 6 - Alternator No. 1 (Courtesy of FAA)



Photograph 7 - Top view of engine (Courtesy of FAA)