

CEN23LA407

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane Overview



Photograph 2 - Lower Fuselage Damage



Photograph 3 - Nose Landing Gear Door Damage



Photograph 4 - Main Landing Gear Actuator



Photograph 5 - Nose Landing Gear Actuator