

CEN23LA416

INVESTIGATION PHOTOGRAPH



Photograph 1 - Left main landing gear strut punctured forward fuselage (Courtesy of Airport Operations)