

CEN23LA417

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Outboard right wing damage (Courtesy of Federal Aviation Administration)



Photograph 2 - Outboard right wing damage (Courtesy of Federal Aviation Administration)