

CEN23LA425

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site viewed from runway (Courtesy of FAA)




Photograph 2 - Tire track leading to airplane (Courtesy of FAA)



Photograph 3 - Accident airplane, right side (Courtesy of FAA)




Photograph 4 - Accident airplane, left side (Courtesy of FAA)



Photograph 5 - Spray valve control lever (Courtesy of Air Tractor)



Photograph 6 - Spray valve lever and rudder pedal (Courtesy of NTSB)



Photograph 7 - Spray valve pushrod and rudder pedal (Courtesy of NTSB)



Photograph 8 - Spray valve pushrod and rudder pedal (Courtesy of NTSB)



Photograph 9 - Spray valve pushrod scrapes (Courtesy of Air Tractor)