

CEN24FA049

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aerial view of the static arm that was impacted by the helicopter (courtesy of Brim Aviation)



Photograph 2 - Aerial view of the static arm that was impacted by the helicopter (courtesy of Brim Aviation)



Photograph 3 - Aerial view of the helicopter (courtesy of Brim Aviation)



Photograph 4 - Aerial view of the helicopter (courtesy of Brim Aviation)



Photograph 5 - View of the pole that the static arm is connected to



Photograph 6 - View of the front of the helicopter



Photograph 7 - View of the rear of the helicopter



Photograph 8 - View of the helicopter during the recovery operation



Photograph 9 - View of the engine during the recovery operation



Photograph 10 - View of the helicopter secured in a trailer during the recovery operation