

CEN24FA164

INVESTIGATION PHOTOGRAPHS



Photograph 1 -Thermally destroyed main wreckage.



Photograph 2 - Thermal damage noted to left wing.



Photograph 3 - Thermal damage noted to right wing.



Photograph 4 - Thermal damage noted to empennage.



Photograph 5 - Thermal damage noted to engine.