

CEN24FA170

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aerial view of accident site (Courtesy of law enforcement)



Photograph 2 - Rear of accident site, wreckage undisturbed (Courtesy of law enforcement)



Photograph 3 - Front of accident site, wreckage undisturbed (Courtesy of law enforcement)



Photograph 4 - Rear of accident site during NTSB examination (Courtesy of NTSB)



Photograph 5 - Left side of accident site during NTSB examination (Courtesy of NTSB)



Photograph 6 - Right wing during NTSB examination (Courtesy of NTSB)



Photograph 7 - Initial impact crater and main wreckage (Courtesy of NTSB)



Photograph 8 - Propeller flange (Courtesy of NTSB)



Photograph 9 - Propeller blade pieces (Courtesy of NTSB)