

Search	Search	Group	Resource
search...	All	Select Here	Select Here

Bookable	Status	Reported By	Date			
N1701Q (aircraft)	Reported	Michael Galloway	05/10/24	Show	Edit	Delete
door stop on right side door does not match up with the hole						
N1701Q (aircraft)	Reported	Michael Galloway	05/10/24	Show	Edit	Delete
screw missing from right wing root fairing						
N1701Q (aircraft)	Reported	Michael Galloway	05/10/24	Show	Edit	Delete
screw missing from wing root fairing right wing						
N1701Q (aircraft)	Reported	Michael Galloway	05/05/24	Show	Edit	Delete
Oil noted on top of cowling after flight						
N1701Q (aircraft)	Reported	Michael Galloway	04/07/24	Show	Edit	Delete
fuel leak from the right wing root when the tank is full. Also there is a loose bolt on the right wheel fairing.						
N1701Q (aircraft)	Reported	Michael Galloway	02/06/24	Show	Edit	Delete
rivet missing inboard right flap						
N1701Q (aircraft)	Reported	Robert Doody	01/19/24	Show	Edit	Delete
Oil appears to have been filled above 6 its, pilot seat tilt mechanism may not be working correctly.						
N1701Q (aircraft)	Reported	George Grall	01/18/24	Show	Edit	Delete
Left upper vent handle fell off parts are in the glove box						

Cancel
Per Page
25 ▼

25

- 25
- 50
- 100
- 200
- 500

Apply

[reset](#)

Bookable	Status	Reported By	Date	
N1701Q.(aircraft)	Reported	Michael Galloway	05/10/24	Q Show Edit Delete
door stop on right side door does not match up with the hole				
N1701Q.(aircraft)	Reported	Michael Galloway	05/10/24	Q Show Edit Delete
screw missing from right wing root fairing				
N1701Q.(aircraft)	Reported	Michael Galloway	05/10/24	Q Show Edit Delete
screw missing from wing root fairing right wing				
N1701Q.(aircraft)	Reported	Michael Galloway	05/05/24	Q Show Edit Delete
Oil noted on top of cowling after flight				
N1701Q.(aircraft)	Reported	Michael Galloway	04/07/24	Q Show Edit Delete
fuel leak from the right wing root when the tank is full. Also there is a loose bolt on the right wheel fairing.				
N1701Q.(aircraft)	Reported	Michael Galloway	02/06/24	Q Show Edit Delete
rivet missing inboard rght flap				
N1701Q.(aircraft)	Reported	Robert Doody	01/19/24	Q Show Edit Delete
Oil appears to have been filled above 6 its, pilot seat tilt mechanism may not be working correctly.				
N1701Q.(aircraft)	Reported	George Grall	01/18/24	Q Show Edit Delete
Left upper vent handle fell off parts are in the glove box				



Squawk for N1701Q (aircraft)

Left upper vent handle fell off parts are in the glove box

Status: Reported and has been resolved.

Date: 18 January 2024

By:  [George Grall](#)

Resolution / Fix: 1-1. Left upper vent handle fell off. Installed vent handle on vent. Ops. checked good.

Last updated by:  [David Johnson](#)

Attachments

 1 GB of 1 GB used.

 last updated: December 05, 2024 09:36 • 759df2e9-2ddf-4fb7-9435-8ef96b47063d • [Revision History](#)



Business solutions that FLY.

FLY Online Tools Copyright © 2010-2024 All Rights Reserved

Squawk for N1701Q (aircraft)

Oil appears to have been filled above 6 its, pilot seat tilt mechanism may not be working correctly.

Status: Reported and has been resolved.

Date: 19 January 2024

By:  [Robert Doody](#)

Resolution / Fix: 1-1. Removed 1/2 cup of excess oil. Marked at 6 quarts presently.

Last updated by:  [David Johnson](#)

Attachments

 1 GB of 1 GB used.

 last updated: December 05, 2024 09:36 • 29f1a352-4889-4576-997a-67f108304738 • [Revision History](#)



Business solutions that FLY.

FLY Online Tools Copyright © 2010-2024 All Rights Reserved

Squawk for N1701Q (aircraft)

rivet missing inboard right flap

Status: Reported and has been resolved.

Date: 06 February 2024

By:  [Michael Galloway](#)

Resolution / Fix: Only found a drain hole. Please take a pick of what you are talking about and we will take care of it. Send pic to [REDACTED] thanks

Last updated by:  [David Johnson](#)

Attachments

 1 GB of 1 GB used.

 last updated: December 05, 2024 09:35 • 9c8e6a0f-a18c-4215-b4e6-29c804399424 • [Revision History](#)



Business solutions that FLY.

FLY Online Tools Copyright © 2010-2024 All Rights Reserved

Squawk for N1701Q (aircraft)

fuel leak from the right wing root when the tank is full. Also there is a loose bolt on the right wheel fairing.

Status: Reported and has been resolved.

Date: 07 April 2024

By:  [Michael Galloway](#)

Resolution / Fix: installed new gasket. Topped off fuel tanks and no leak noted

Last updated by:  [David Johnson](#)

Attachments

 1 GB of 1 GB used.

 last updated: December 05, 2024 08:42 • ef54d544-0db6-4713-a37a-4e902261ade8 • [Revision History](#)



Business solutions that FLY.

FLY Online Tools Copyright © 2010-2024 All Rights Reserved

Squawk for N1701Q (aircraft)

Oil noted on top of cowling after flight

Status: Reported and has been resolved.

Date: 05 May 2024
By:  [Michael Galloway](#)
Resolution / Fix: Oil Dipstick was left loose
Last updated by:  [David Johnson](#)

Attachments

 1 GB of 1 GB used.

 last updated: December 05, 2024 09:33 • e865cbcf-7fc1-468f-af1f-ea04a8515abd • [Revision History](#)



Business solutions that FLY.

FLY Online Tools Copyright © 2010-2024 All Rights Reserved

Squawk for N1701Q (aircraft)

door stop on right side door does not match up with the hole

Status: Reported and has been resolved.

Date: 10 May 2024

By:  [Michael Galloway](#)

Resolution / Fix: door pin was bent. Adjusted pin and OPS checks good

Last updated by:  [David Johnson](#)

Attachments

 1 GB of 1 GB used.

 last updated: December 05, 2024 09:18 • 7df31198-a5b7-48d4-92c5-c1e51050d0b3 • [Revision History](#)



Business solutions that FLY.

FLY Online Tools Copyright © 2010-2024 All Rights Reserved

Squawk for N1701Q (aircraft)

screw missing from right wing root fairing

Status: Reported and has been resolved.

Date: 10 May 2024
By:  [Michael Galloway](#)
Resolution / Fix: Replaced Screw
Last updated by:  [David Johnson](#)

Attachments

 1 GB of 1 GB used.

 last updated: December 05, 2024 09:31 • ca30316a-fb5d-4848-b3e2-fdb45c2dc9c4 • [Revision History](#)



Business solutions that FLY.

FLY Online Tools Copyright © 2010-2024 All Rights Reserved

Squawk for N1701Q (aircraft)

screw missing from wing root fairing right wing

Status: Reported and has been resolved.

Date: 10 May 2024
By:  [Michael Galloway](#)
Resolution / Fix: Replaced Screw
Last updated by:  [David Johnson](#)

Attachments

 1 GB of 1 GB used.

 last updated: December 05, 2024 09:32 • b7b89efc-bec4-4bb7-ae4e-188866b201d3 • [Revision History](#)



Business solutions that FLY.

FLY Online Tools Copyright © 2010-2024 All Rights Reserved