

CEN24FA212

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (courtesy of local law enforcement)



Photograph 2 - Accident site



Photograph 3 - Engine and propeller



Photograph 4 - Propeller



Photograph 5 - Oil quick drain as found at accident site



**Photograph 6 - Engine examination - connecting rods and bearings
(Courtesy of Continental Aerospace Technologies)**



**Photograph 7 - Engine examination - No. 5 connecting rod journal
(Courtesy of Continental Aerospace Technologies)**