

CEN24FA260

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aerial view of accident site location



Photograph 2 - N795LA Accident Airplane



Photograph 3 - N795LA Missing Tail Wheel Assembly (Source: Operator)



Photograph 4 - N795LA Tail wheel assembly after recovery




Photograph 5 - N795LA Paint and fiberglass debris



Photograph 6 - N6177J Initial ground impact



Photograph 7. N6177J Debris field



Photograph 8. N6177J Separated outboard left wing (Source: FAA)



Photograph 9. N6177J Separated outboard left wing



Photograph 10. N6177J Separated left wing structure with exemplar wheel assembly



Photograph 11. N6177J Left horizontal stabilizer