

CEN24FA298

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Entire aircraft during examination (NTSB Photo)



Photograph 2 - Tail surfaces showing rotor impact mark (NTSB Photo)



Photograph 3 - Tail boom and tail surfaces (NTSB Photo)



Photograph 4 - Separated rotor drive coupling (NTSB Photo)



Photograph 5 - Rotor head during examination (NTSB Photo)



Photograph 6 - Engine during the examination (NTSB Photo)