

CEN24FA305

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of accident site location (Source: Textron Aviation)**



**Photograph 2 - View of Accident Site Location (Source: Textron Aviation)**



**Photograph 3 - Separated Elevator Section (Source: Textron Aviation)**



**Photograph 4 - Left Side View of Engine (Source: Lycoming)**



**Photograph 5 - Right Side View of Engine (Source: Lycoming)**



**Photograph 6 - View of Propeller Blades (Source: Lycoming)**