

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN24LA327

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main wreckage



Photograph 2 - Engine



Photograph 3 - AV8OR personal electronic device



Photograph 4 - Initial point of impact



Photograph 5 - Starter motor impact signature



Photograph 6 - Propeller



Photograph 7 - Propeller blade



Photograph 8 - Propeller blade