

CEN24LA012

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of the Federal Aviation Administration)



Photograph 2 - Right Wing Damage (Courtesy of the Federal Aviation Administration)



Photograph 3 - Left Wing Damage (Courtesy of the Federal Aviation Administration)



Photograph 4: Blown Fuse (Courtesy of the Pilot/Aircraft Owner)