

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN24LA014

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at Accident Site (Courtesy of Airplane Owner)



Photograph 2 - Right Main Landing Gear and Wheel Assembly (Courtesy of Airplane Owner)



Photograph 3 - Fire Damage to Lower Right Wing (Courtesy of Airplane Owner)



Photograph 4 - Right Brake Inner Linings with Pressure Plate (Courtesy of Airplane Owner)



Photograph 5 - Right Brake Linings (Courtesy of Aviation Mechanic)



Photograph 6 - Left Brake Assembly with Temperature Indicators (Courtesy of Airplane Owner)