


CEN24LA017

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Pitch Change Link Damage (Courtesy of the Operator)



Photograph 2 - Stabilizer Damage (Courtesy of the Operator)