

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN24LA018

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (Courtesy of FAA)



Photograph 2 - Fractured actuator (courtesy of pilot)