

CEN24LA023

INVESTIGATION PHOTOGRAPH



Photograph 1 - Damaged left wing (Courtesy of the Federal Aviation Administration)