



Laura Abraham
Air Safety Investigator
Central Region

Date: 14 January 2025

Subject: CEN24LA038, Email Correspondence

Contact: Mr. William Holland, Airplane Owner and Pilot

Mr. Holland stated that when he received the AXSport Propeller, there were no assembly instructions, so he assembled the propeller from memory the way the propeller manufacturer showed him at an airshow the year prior in 2022. He installed the propeller on his airplane in May of 2023. In August of 2023, all 3 propeller blades were replaced because one of the propeller blades kept backing out of the hub. The manufacturer sent him 3 new blades with retention pins. After the 3 new blades were installed, he balanced the propeller to 0.02 inches per second in accordance with the propeller operator's manual.

---end summary---