

CEN24LA043

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Rear view of airplane (Courtesy of Airport Manager)**



**Photograph 2 - Right main landing gear separated (Courtesy of Airport Manager)**



**Photograph 3 - Deformation noted to right wing (Courtesy of Airport Manager)**



**Photograph 4 - Deformation noted to right wing main spar (Courtesy of Airplane Owner)**