

CEN24LA051

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Engine Mount and Firewall (Courtesy of Pilot)



Photograph 2 - Lower Right Fuselage Damage (Courtesy of Pilot)