

CEN24LA052


INVESTIGATION PHOTOGRAPHS




Photograph 1 - Front view of accident airplane (Courtesy of FAA)



Photograph 2 - Side view of accident airplane (Courtesy of FAA)



**Photograph 3 - Left magneto distributor block and rotor.
Note arcing damage to electrodes and oil saturated felt in the center of the distributor.
(Courtesy of NTSB)**



Photograph 4 - Right magneto distributor block
Note arcing damage to electrodes and oil saturated felt in the center of the distributor.
(Courtesy of NTSB)