

CEN24LA054

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left Horizontal Stabilizer Damage (Courtesy of Airplane Operator)



Photograph 2 - Upper Surface Damage of Left Horizontal Stabilizer (Courtesy of Operator)