

CEN24LA059

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of the left side of the airplane (Courtesy of the Federal Aviation Administration)**



**Photograph 2 - View of the rear of the airplane (Courtesy of the Federal Aviation Administration)**



**Photograph 3 - View of the right side of the airplane (Courtesy of the Federal Aviation Administration)**



**Photograph 4 - View of the fractured engine mount (Courtesy of Lubbock Aero)**



**Photograph 5 - View of the fractured engine mount (Courtesy of Lubbock Aero)**