

CEN24LA065

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of Federal Aviation Administration)



Photograph 2 - Fuel Pump Assembly (Courtesy of NTSB)



Photograph 3 - Fuel Pump Assembly Screw Measurement (Courtesy of NTSB)



Photograph 4 - Fuel Pump Assembly Internal Aneroid (Courtesy of NTSB)