

CEN24LA082

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Deformation noted to rudder (Courtesy of FAA)



Photograph 2 - Wheel impression noted from the runway to the wreckage (Courtesy of FAA)



Photograph 3 - Corrosion noted to the anchor bolts (Courtesy of FAA)