

CEN24LA086

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane on ramp (Courtesy of FAA)



Photograph 2 - Lower fuselage and gear door damage (Courtesy of FAA)



Photograph 3 - Lower fuselage and flap damage (Courtesy of FAA)



Photograph 4 - Lower fuselage and flap damage (Courtesy of FAA)