

CEN24LA097

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Deformation noted to the fuselage (Courtesy of Airport Manager)



Photograph 2 - Deformation noted to main rotor blade (Courtesy of Airport Manager)