

CEN24LA108

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front of airplane (Courtesy of FAA)



Photograph 2 - Right wing damage (Courtesy of FAA)



Photograph 3 - Fuel selector handle OFF (Courtesy of FAA)